#### DOCUMENT RESUME

ED 097 584 CE 002 404

TITLE Aircraft Assembly, Riveting and Surface Repair 2;

Sheet Metal Work 2: 9855.03.

INSTITUTION Dade County Public Schools, Miami, Fla.

PUB DATE Feb 74

NOTE 18p.; An Authorized Course of Instruction for the

Quinmester Program

EDRS PRICE MF-\$0.75 HC-\$1.50 PLUS POSTAGE

DESCRIPTORS \*Assembly (Manufacturing); Course Content; Course

Objectives: \*Curriculum Guides: Job Skills: Metallurgy: \*Metal Working Occupations: Post

Secondary Education; Repair; Secondary Grades; Sheet

Metal Work: \*Trade and Industrial Education

IDENTIFIERS Aircraft: \*Quinmester Program

ABSTRACT

This course provides experience in assembly techniques, including repairs on aircraft structures, utilizing all methods from basic layout to surface protection of finished parts. Course content includes goals, specific objectives, metal fasteners, general structural repairs, and aircraft assembly. A bibliography and post-test are appended. Prior to taking this course the student must display mastery of the skills indicated in "Aircraft Assembly, Riveting and Surface Repair 1". (NH)

AUTHORIZED COURSE OF INSTRUCTION FOR THE

US OEPARTMENT OF HEALTH.

EDUCATION & WELFARE
NATIONAL INSTITUTE OF
EDUCATION

THIS DOCUMENT HAS BEEN REPRO
DUCED EXACTLY AS RECEIVED FROM
THE PERSON OR ORGANIZATION ORIGIN
ATING IT POINTS OF VIEW OR OPINIONS
STATED DO NOT NECESSARILY REPRE
SENT OFFICIAL NATIONAL INSTITUTE OF
EDUCATION POSITION OR POLICY

Course Outline

SHEET METAL WORK 2 - 9855 (Aircraft Assembly, Riveting and Surface Benair 2)

Denartment 40 - Ouin 9855.03

# DADE COUNTY PUBLIC SCHOOLS 1450 NORTHEAST SECOND AVENUE MIANI, FLOPIDA 33132

## BEST CON ANALONE

Course Outline

SHEET METAL MORK 2 - 9855 (Aircraft Assembly, Riveting and Surface Repair 2)

Department 48 - Ouin 9855.03

county office of VOCATIONAL AND ADULT EDUCATION



#### THE SCHOOL BOARD OF DADE COUNTY

Mr. G. Holmes Braddock, Chairman Mr. William H. Turner, Vice-Chairman Mrs. Ethel Beckham Mr. Alfredo G. Duran Mrs. Phyllis Miller Mr. Robert Renick Dr. Ben Sheppard

Dr. E. L. Whigham, Superintendent of Schools
Dace County Public Schools
Miami, Florida 33132

February, 1974

Published by the School Board of Dade County



#### Course Description

9855 48 9855.03 Aircraft Assembly, Riveting and Surface Repair 2

State Category Number Number Sumber

This is an advanced quin course in assembly technique including repairs on aircraft structures, utilizing all methods from basic layout to surface protection of finished parts. This is a three quinmester credit course.

Indicators of success: Prior to entry into this course the student must display mastery of the skills indicated in Aircraft Assembly, Piveting and Surface Remain 1 (9855.02).

Clock Hours: 135



#### **PREFACE**

The following course outline is a third quinmester course.

Prior to entry into this course, the vocational student must display mastery of the skills indicated in Aircraft Assembly, Riveting and Surface Repair 1 (9855.02). This course outline serves as a guide to the instructor who teaches in the field of sheet metal.

This advanced course is composed of four blocks of instruction, which are subdivided into several units each. It is 135 hours in length.

Emphasis is placed on the use of visual aids, mock-ups, cutaways, transparencies, films, various instructional sheets and manipulative shop practice.

Upon completion of this course, the student will have a general overall basic understanding of aircraft structure, aircraft riveting, surface repairs, and surface protection of metal.

This outline was developed through the cooperative efforts of the instructional and supervisory personnel, the Quinmester Advisory Committee and the Vocational Curriculum Materials Service, and has been approved by the Dade County Vocational Curriculum Committee.



## TABLE OF CONTENTS With Suggested Hourly Breakdown

	rage
PREFACE	111
BLOCK	
I. METAL FASTENERS (24 Hours) Riveting	1
II. GENERAL STRUCTURAL REPAIRS (84 Hours) Making Structural Repairs	
III. AIRCRAFT ASSEMBLY (27 Hours) Checking Alignment of Structures	1
IV. QUINMESTER POSTTEST	
APPENDIX: OUINMESTER POSTTEST SAMPLE	7



#### **GOALS**

The student must be able to demonstrate:

- 1. The ability needed to do aircraft structural repairs.
- 2. The ability to check, align and assemble aircraft sections.
- 3. The ability to perform proper riveting on aircraft sections and structural parts.
- 4. The ability to assume the responsibility inherent in the aviation sheet metal technician's occupation.



#### SPECIFIC BLOCK OBJECTIVES

#### BLOCK I - METAL FASTENERS

The student must be able to:

- 1. Demonstrate the proper methods of drilling holes for riveting.
- 2. Exhibit the ability to prepare the metal before riveting.
- 3. Demonstrate the proper use of hand and power tools for riveting.
- 4. Explain the standards for acceptable rivets.

#### BLOCK II - GENERAL STRUCTURAL REPAIRS

The student must be able to:

- 1. Exhibit the ability to make proper repairs to longerons and formers.
- 2. Demonstrate the ability to make proper repairs on spars, ribs and bulkhead leading and trailing edges.
- 3. Explain the proper method of scaling remain areas.
- 4. Exhibit the ability to make proper remains to ailerons, flaps, elevators, rudders, stabilizers and tabs.

#### BLOCK III - AIRCRAFT ASSEMBLY

The student must be able to:

- 1. Exhibit the ability to read and understand fuselage and wing station numbering systems.
- 2. Explain the proper methods of checking alignment of gear, wing, tail and fuselage after structure remains.
- 3. Demonstrate the ability to assemble aircraft parts after repairs.

#### BLOCK IV - QUINTESTED POSTTEST

The student must be able to:

1. Satisfactorily complete the quinmester posttest.



#### Course Outline

## SHEET METAL WORK 2 - 9855 (Aircraft Assembly, Riveting and Surface Repair 2)

#### Department 48 - Quin 9855.03

#### I. METAL FASTENERS

- A. Riveting
  - 1. Burring edges of metal
  - 2. Drilling holes for rivets
    - a. Hand drills
    - b. Power drills
  - 3. Surring drilled holes
  - 4. Grinding drill bits
- B. Installing Rivets
  - 1. Driving rivets
    - a. By hand
    - b. With rivet oun
    - c. With squeeze riveter
  - 2. Bucking rivets
  - 3. Inspecting rivets
  - 4. Removing and replacing rivets

#### II. GENERAL STRUCTURAL REPAIRS

- A. Making Structural Repairs
  - 1. Spars
  - 2. Bulkhead
  - 3. Ribs
  - 4. Leading edges
  - 5. Trailing edges
  - 6. Londerons and formers
  - 7. Scaling repair areas
- B. Making Remairs to Flight Controls
  - 1. Ailerons
  - 2. Flaps
  - 3. Stabilizers
  - 4. Rudders
  - 5. Floyators
  - 6. Control tabs
  - 7. Dalancing surface control
  - 3. Attaching support jigs and fixtures

#### III. AIRCPAFT ASSETELY

- 4. Checking Alienment of Structures
- B. Pooding Stations' Diagrams
  - 1. Fuselage station numbering systems
  - 2. Mind station numbering systems



- Using Manufacturer's Manuals
  Procedure to measure angle of incidence, dihedral
  Checking alignment, gear, wing, tail
- IV. QUINMESTER POSTTEST



### BIBLIOGRAPHY (Aircraft Assembly, Riveting and Surface Repair 2)

Basic References:

None

#### Supplementary References:

- 1. <u>Airframe and Power Plant Mechanics Airframe Handbook AC-65-15</u>. F.A.A. Washington, D.C.: U.S. Government Printing Office, 1972. Pp. 538.
- 2. Airframe and Power Plant Mechanics Géneral Handbook AC-65-9.

  F.A.A. Washington, D.C.: U.S. Government Printing Office,
  1970. Pn. 497.
- 3. Airframe Mechanics Unitten Exam Guide. Fort North, Texas:
  Acme School of Aeronautics, 1968. Pp. 63.
- 4. Bent, Ralph D., and McKinley, James L. Aircraft Maintenance and Renair. New York: McGraw-Hill Book Company, 1955. Pp. 444.
- 5. Federal Aviation Administration. Acceptable Methods, Techniques and Practices Aircraft Alteration Advisory Circular 43-13-2.

  Washington, D.C.: U.S. Government Printing Office, 1965.
  Pp. 74.
- 6. Acceptable Methods, Techniques and Practices Aircraft
  Inspection and Repair Advisory Circular 43-13-1. Washington,
  D.C.: U.S. Government Printing Office, 1965. Pp. 232.
- 7. Giachino, J. W. Aircraft Sheet Metal Mork. Penria, Illinois: The Manual Arts Press, 1942. Pn. 123.
- 8. Leavell, Stuart, and Bunnay, Stanley. <u>Standard Aircraft Handbook</u>. Los Angeles: Aero Publishers, Inc., 1952. Pn. 159.
- 9. Nista, Albert H. Aircraft Riveting. New York: McGraw-Hill Book Co. Inc., 1946. Pp. 160.
- 10. Northrun Institute of Technology. Basic Science for Aerospace Vehicles. 3rd ed. New York: Hchraw-Hill Book Company, 1963. Pp. 320.
- 11. Overby, Charles A. Aircraft and Missle Dosign Maintenance Handbook. New York: The Mac Millan Company, 1960. Pr. 320.



- 12. United States Dept. of Air Force. Airframe Maintenance, Airforce Manual 52-11. Washington, D.C.: U.S. Government Printing Office, 1964.

  Pp. 314.
- 13. U.S. Naval Air Technical Training Command. <u>Aircraft Structural Maintenance</u>, Navpers 19303B. Washington, D.C.: U.S. Government Printing Office, 1969. Pp. 414.

#### Films:

- 1. Airplane Structures. 16 mm. 45 min. Black. Sound. Jan Handy.
- 2. Building PBY. 16 mm. 45 min. Black. Consolidated Aircraft Corporation.
- 3. How to Rivet Aluminium. 16 mm. 20 min. Black. Sound. Alcoa.
- 4. Forming Aluminium. 16 mm. 20 min. Plack. Alcoa.



A P P E N D I X

Quinmester Posttest Sample



#### QUINMESTER POSTTEST

Name			Date Score
			Multiple Choice Test Items
Only	one	of t	t needs a word, a figure, or a phrase to make it correct. the choices listed is correct. Place the letter of the choice the space provided at the left edge of the sheet.
	1.	Size	making repairs, you replace rivets with those of the same e and strength whenever nossible. If the rivet hole becomes arged, you may:
		b. c.	Squeeze the rivet in a vise to enlarge shank, then install in the enlarged hole. Urill the hole for the next larger rivet size making sure minimum edge distance and spacing are maintained. Install the same size rivet as the rivet will swell and fill the hole. Replace rivet with a larger aircraft holt.
	2.	The	type of material that the rivet is made of is identified by:
		C.	Diameter of rivet Type of rivet head Mark on rivet head Color of material
	3.		retain 83% of the material's tensile strength, the rivet spacing wild be:
		С.	At least 1/2 inch chacing for all rivets Four times the diameter of the rivet Two times the diameter of the rivet Three times the diameter of the rivet
· · ·	4.		et holes are usually drilled larger than the rivets. This is ally around:
		h. C.	.001 inch .003 inch .02 inch .008 inch
and specifical shades	5.	If thi	you were doing to rivet through two pieces of metal whose combined ckness was .064 inch, the shank of the rivet should be:
			.064 plus 1 1/2 times diameter of the rivet 1 1/2 times the diameter of the rivet 1 1/2 times .064 .064 plus twice the diameter of the rivet



If you had some 2017D rivets that had been aging for two hours after quenching: a. You could use them providing they had not exceeded four hours You could not use them because 175 rivets should be used within one hour after quenching You could use them providing they had not exceeded two hours of aging d. You could not use them because 2017D rivets should be used within 30 minutes after quenching. When riveting two sheets of aluminium together and one is thicker than the other, the formed head of the rivet should: Go on the side of the thinnest sheet Go on the side of the thickest sheet c. It makes no difference which side the pre-formed head goes on Go on either side, if the paper tools are being used to buck the rivet. Aluminium alloy rivets 25 (1100) should never be used on structural. members of aircraft: Because they become brittle with age They are too soft b. They are two hard to drive and might damage the structural Because they can only be used in shear To make a splice plate, riveting a piece 7.080 aluminium stock to .040 skin with 1/8 rivets, the length of the rivets would be: 1/3" a. b. 1/4" 5/16" C. d. 3/8" 10. A properly installed rivet is designed to withstand which of the following stresses? Shear a. Compression b. Tension d. Torsion When an aircraft fuselage is damaged, and a noticeable twist or distortion is apparent, the final step taken to remain this is to: Use a "port-a-power" to bring bulkheads back into place. Remove the damaged section and replaced with factory approved

C.

with the remain

Cut out all damage area immediately

Place the fuselage in a factory approved "iig" and then proceed

12.	If you plan to use 1/8 inch rivets on a metal surface patch with a single row pattern, what will be the minimum overlap of the metal?
	a. 7/8 inch b. 1 inch c. 1/2 inch d. 3/4 inch
13.	If a bulge is found between two riveted sheets, the most probable cause is that:
	<ul> <li>a. The rivets have been overdriven</li> <li>b. The rivets are too long</li> <li>c. The rivets are age hardened and not heat treated prior to use</li> <li>d. The sheets were not held together properly during the riveting operation.</li> </ul>
14.	Members should be carefully examined for the presence of sharp nicks and deep scratches which may have resulted from service. Care must be taken to smooth out all of these found in order to:
	<ul> <li>a. Remove stress concentrations that may cause failure</li> <li>b. Keen the metal from corroding at these snots</li> <li>c. Enable the mart to mass inspection</li> <li>d. Prevent the member from splitting</li> </ul>
15.	When remaining control surface, especially on high performance aircraft, care should be exercised that the remains do not involve the addition of weight aft of the hinge line. Such procedure may:
	<ul> <li>a. Induce flutter of the control surface</li> <li>b. Adversely disturb the static balance of the control surface</li> <li>c. Adversely disturb the dynamic balance of the control surface</li> <li>d. All of the above are correct</li> </ul>
16.	Which of the following is true concerning control surface movement?
	a. Movement is measured in inches or degrees b. Specification can be found in the type certificate data sheet or aircraft specification
	<ul> <li>They have nositive stops</li> <li>All of the above are correct</li> </ul>
17.	The use of self-tanning screws in aircraft primary structural assemblies is:
	a. A common practice b. Forbidden
	b. Forbidden c. Meconmended in blind areas, with two Chreads showing d. Allowed on aircraft with never excess speed less than 150 mph

18.	What is the effect on a high-shear rivet that is under-bucked?
	a. It will be loose in the hole b. The same as on a hollow shank rivet c. The collar will not be properly seated d. Its shear strength will be reduced
19.	Semi-monocoque fuselage consists of vertical members covered with a structural skin. The longitudinal members are called:
	<ul><li>a. Frames</li><li>b. Stringers</li><li>c. Bulkheads</li><li>d. Formers</li></ul>
20.	Spars also called beams are:
	<ul> <li>a. Principal chord structural members</li> <li>b. Main spanwise members of the wing, stabilizers and other airfoils</li> </ul>
	<ul><li>c. Oval shape members of the fuselage</li><li>d. Front section of a wing, stabilizer or other airfoils</li></ul>
21.	Ribs are the principle:
	<ul> <li>a. Chordwise structural members</li> <li>b. Main spanwise members</li> <li>c. Main vertical members</li> <li>d. All of the above</li> </ul>
22.	The internal structure of the semi-monoconue fuselage is made up of longitudinal members called:
	a. Longerons & stringers b. Formers c. Bulkheads & rings d. All of the above
23.	Lightening holes are sometime cut in an aircraft's structural parts to:
	a. Reduce weight b. Increase lift c. Decrease drag d. Increase flexibility
24.	Trailing edges of an airfoil are:
	<ul> <li>a. Structural members</li> <li>b. Non-structural members</li> <li>c. Only two per aircraft</li> <li>d. None of the above is correct</li> </ul>



- 25. When repairs on a control surface add weight fore or aft of the hinge center line, the control surface must be:
  - a. Painted to identify repair section
  - b. Hever installed without the approval of the inspector
  - c. Rehalanced
  - d. Properly rerig and then install

#### ANSWER KEY 10 QUINMESTER POSTTEST

#### Multiple Choice Test Items

13. d

14. a b 1. 15. d 2. С 16. d d 3. 17. b 4. С 18. C 5, ล 19. h 6. d 20. b 7. b 21. а 8. b 22. d 9. С 23. a 10. a 24. b 11. c 25. С 12. c